

Number: HGHT05834062

Date:

Dec 14, 2018

Applicant: SHAOXING IDEAL TEXTILE CLOTHING CO., LTD

RM2102, NO.1 FUSHEN MANSION, DIDANG NEW CITY, SHAOXING CITY, ZHEJIANG PROVINCE,

CHINA

Attn: LI MING

Sample Description As Declared:

No. Of Sample : One (1)

Fibre Content : 100% Polyester Material : Knitted Fabric

Finishing : -

End Uses : Upholstery
Colour : Blue
Style No. : GLOBALE

Order No./PO No. : Buyer's Name : Manufacturer's Name : -

Applicant's Provided Care Instruction/Label:

_

Date Received/Date Test Started: Dec 03, 2018

Prepared And Checked By:

For Intertek Testing Services Ltd., Hangzhou

Vivian Zhao Manager





Number: HGHT05834062

Conclusion:

Color Fastness To Crocking	М
Color Fastness To Light	#
Snagging Resistance	М
Bursting Strength As Received	М
Pilling Resistance As Received	#
Abrasion Resistance	#

Note : M = Commercially AcceptableF = Fail # = No Comment

N/A = Not Applicable

Prepared And Checked By: For Intertek Testing Services Ltd., Hangzhou

Vivian Zhao Manager





			Number:	HGHT05834062
Гes l	ts Conducted (As Requested By The Applicant) Color Fastness To Crocking (AATCC 8-2016):			
	Dry Wet	4.5 4.5		
2	Color Fastness To Light (AATCC 16.3-2014, Option 3,	Xenon-Arc Lamp):		
	40 AATCC Fading Unit (AFU) Exposure Grade	4		
3	Snagging Resistance (ASTM D3939/D3939M-2013 (R2	2017), 600 Revolut	ions Test In	ICI Mace Snag Tester):
	Along Wales Rating	4		
	Along Courses Rating	4		
	Overall Average Rating	4		
1	Remark: Visual Rating Standards: ICI Photographic Sr Bursting Strength As Received (ASTM D3786/D3786M			
	Over	80.0 lbf/in ²		
5	Pilling Resistance As Received (ASTM D3512/D3512M-	-10 (2014), Rando	m Tumbler):	
	After A 30-Minute Test Rating	4		
	Remark : Viewing Option - ASTM Lightbox			



Number: HGHT05834062

Tests Conducted (As Requested By The Applicant)

Abrasion Resistance (ASTM D4966-12(2016), Option 1, Martindale Abrasion And Pilling Tester, 9 kPaTotal Pressure):

Resistance

Face Side Over 60,000 Rubs

End of Report

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct.

This report shall not be reproduced except in full, without written approval of the laboratory.